


Appendix D: Observed Land Damage Map



LEGEND

- Minor land damage but no observed liquefaction
- Liquefaction but no lateral spreading
- Moderate lateral spreading
- Severe lateral spreading

NOTES:
 1. Low resolution aerial photographs sourced from Google Earth (Copyright: 2009).
 2. The land damage assessment is based on preliminary inspections of individual properties undertaken by Tonkin & Taylor Ltd staff following the 22 February 2011 aftershock.
 3. The areas of damage are simplified for schematic purposes.



Tonkin & Taylor
 Environmental and Engineering Consultants
 30 Parkhouse Road, Wilton, Christchurch
 www.tonkin.co.nz

DRAWN	NSW	Oct 11
DRAFTING CHECKED	RAP	11
APPROVED	HTF	11
CAD FILE	\\52000.301-D1.dwg	
SCALES	(AT A3 SIZE)	
NTS		
PROJECT No.	52000.301	

CHRISTCHURCH CITY COUNCIL
 GEOLOGICAL INTERPRETATIVE REPORT
 CHRISTCHURCH CENTRAL CITY
 Observed Land Damage Map